



# AquaReef 290 195 300 395 400

## Trouble Shooting

---

### **BUBBLES ARE COMING OUT THE OUTLET INTO THE AQUARIUM**

1. The water level in the sump is too low. Check specific gravity after topping up to the correct level.

Note: We recommend an auto top up unit such as an Aqua One AquaFill to automatically top up from the built in reservoir.

2. The elbow has become loose or come off the pump inlet.

3. Note that in the first few days of running a new protein skimmer (sold separately), there may be an excess of bubbles escaping into the tank. This should settle within a week or two as the skimmer is run in.

2. There is a blockage in the drain pipe. Remove air intake and check pipe for blockage.

to allow the removal of the support which in turn allows the sump to be removed.

3. Adjust the siphon break tube so that the open end of the tube is near the water level so that it is not splashing.

### **WATER FLOW INTO THE AQUARIUM HAS DROPPED**

1. Pump needs to be cleaned. Refer to maintenance instruction provided with pump.

2. Outlet is blocked. Remove and clean the flexible outlet.

### **DRAIN PIPE OR WEIR IS NOISY**

1. Air intake may be blocked. Remove and rinse in fresh water, salt build up can cause a small blockage