



# MiniSkin Protein Skimmer

## Trouble Shooting

### **SKIMMER ISN'T PRODUCING ENOUGH BUBBLES**

1. Ensure airline control valve is open sufficiently.
2. Airstone may need replacing.

### **SKIMMER IS COLLECTING NO WASTE**

1. Ensure sufficient air is entering the pump. Refer above for solution.
2. Ensure pump is running correctly. Check and clean the impeller.

### **COLLECTION CUP IS OVERFLOWING**

1. Check airline drain. Replace if necessary.
2. Ensure air flow is not too high. Waste exiting the skimmer should be coffee coloured. If the waste is very watery/light in colour, decrease the flow of air being supplied to the airstone.
3. Check the carbon cartridge and replace if necessary. If the cartridge becomes blocked, the water level in the skimmer may rise forcing more bubbles to flow into the collection cup.