



NanoSkim Protein Skimmer

Trouble Shooting

SKIMMER ISN'T PRODUCING ENOUGH BUBBLES

1. Ensure air intake is attached firmly to the inlet of the pump.
2. Airstone may need replacing.

SKIMMER IS COLLECTING NO WASTE

1. Ensure the water level is high enough. Adjust the outlet taps to raise water level.
2. Ensure pump is running correctly. Check and clean the impeller.

COLLECTION CUP IS OVERFLOWING

1. Check airline drain. Replace if necessary.
2. Ensure water level is not too high in the skimmer. Waste exiting the skimmer should be coffee coloured. If the waste is very watery/ light in colour, decrease the flow of air being supplied to the airstone.
3. Check the carbon cartridge and replace if necessary. If the cartridge becomes blocked, the water level in the skimmer may rise forcing more bubbles to flow into the collection cup.